SEP 0 9 1993 ENGINEERING DATA TRANSMITTAL

Page 1 of ______ 1. EDT Nº 141686

2. To: (Receiving Organization) Environmental Engineering			g	3. From: (Originating Organization) Environmental Restoration Safety Support			4. Relate	d EDT No.	. :		
5. Proj./Prog./Dept./Div.:				6. Cog. Engr.:			7. Purchase Order No.:				
N/A					J. M. Fra	in			N/	Α	
8. Or	iginato	r Remarks:					24 25 36 21 18 29 30 31 ED	9. Equip.	/Componer	nt No.:	
	Appro	val/Rel	ease			20212223	2420		N/	A	
					6	3920212223	13.58°	10. Syste		-	
						(Mart 4)	=		<u>N/</u>	<u>A</u>	
11. Re	eceiver	Remarks:			167	RECEIVED NO.	993 %	12. Major		-	
					115	RECEIV FD8c	ED &		N/		
					1/25	· ·	3/	13. Permi			ion No.:
					/2	,	.4/	· · · · · · · · · · · · · · · · · · ·	N/		
						1016910	G 7 5 7	14. Requi			
						6079	3/	A	ugust 2	2, 1993	
15.				DATA	TRANSMITTED			<u>(F)</u>	(G)	(H)	(1)
(A)				(C)	(D)			Impac	Reaso n for	Origi -	Receiv -
Item No.	(B) I	Document/D:	rawing No.	Sheet	Rev.		or Description of Transmitted	t	Trans -	nator Dispo	er Dispo-
NO.				No.	No.		,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Level	mitta	sitio	sition
									,	n	
1	WHC-	-SD-EN-S	AD-026		0	i carety modernment			1	1	
						Storage o		ESQ	and		
						the 100-F	ted Soil at		2		
	-					0110 100 1	711 Cu				
16.					1. 1.	KEY		_ 1			
	act Lev			Reason for	Transmittal	(G)		Dispositio	n (H) & (I)	
1, 2, MRP 5.	3, or 4 43)	4 (see	1. Approva 2. Release 3. Informa Required)	5. Pos	iew t-Review st. (Receipt	Acknow.	1. Approved 2. Approved w/ 3. Disapproved	comment 5	Review Review Receipt	ed w/comm	ent
(G)	(H)	17.		(6-		URE/DISTRIBUT				(G	(H)
Rea	Dis	(J) Name	(K	(Sec Signatur		el for require		ignature	(L) Date	Rea	Dis
- son	p.	Λ·V		M) MSIN			(M)		(2)	- Sor	p.
1		Çog.Eng.	J. M. Frain	Ochar	ulk dia no	-04 ERSS	N. R. Kerr /72	2	н4-		
1		Cog. Mgr.	G. C. Henc	kel III	He He	5-04 RRSA	J. J. Zimmer	MA	1 AR	67 1	
1		QA T. L.	Bennington	12 mg	11 5-2A-9	16-16	Q)	H4	-67	
1		Safety M.	A. Tredway	ZOOT		-54					
1		Env. K. A	. Gano	286	9 40/93 XC)-21					
1		Radiation	K. A. Smit	hyslen	• /	-06					
1		Ind. Safe	ty L. C. Ha	slam A	2/1/50	-51					
18.		. 1	// 19.	0	0	20.	-016-11	21. DOE A	PROVAL (if requir	ed)
J. A. Locklair for Frain Project Signature of EDT q-1-q S Originator 19. 20. 21. DOE APPROVAL (if require Ltr. No. II) Approved W/comments Engineer's Manager 20. 21. DOE APPROVAL (if require Ltr. No. II) Approved W/comments Engineer's Manager 21. DOE APPROVAL (if require Ltr. No. II) Approved W/comments Engineer's Manager 22. 21. DOE APPROVAL (if require Ltr. No. II) Approved W/comments Engineer's Manager 23. 24. 25. 26. 27. 27. 27. 27. 27. 27. 27. 27. 27. 27											

SUPPORTING DOCUMENT 1. Total Pages 42 2. Title 3 Number 4. Rev No. WHC-SD-EN-SAD-026 Safety Assessment for Storage of the Contaminated 0 Soil at the 100-F Area APPROVED FOR PUBLIC RELEASE Of Burhland Of Burhland 5. Kev Words 6. Author Name: J. A. Lockila/ Safety assessment Contaminated soil Soil storage unit Organization/Charge Code 29550/PG22F 7. Abstract This safety assessment addresses the hazards associated with storage of contaminated soil from a liquid waste disposal site on a temporary or semipermanent basis. PURPOSE AND USE OF DOCUMENT - This document was prepared for use within the U.S. Department of Energy and its contractors. It is to be used only to perform, affect, or integrate work under U.S. Department of Energy contracts. This document is not approved for public release until reviewed. RELEASE STAMP PATENT STATUS - This document copy since it is transmitted in advance of patent clearance, is made available in confidence solely for use in performance of work under contracts with the U.S. Department of Energy. This document is not to be published nor its contents otherwise disseminated or used for purposes other than the profile of the published patents. specified above before patent approval for such release or use has OFFICIAL RELEASE been secured, upon request, from the Patent Counsel, U.S. Department of Energy Field Office, Richland, WA. BY WHC DATE SEP 09 1993 DISCLAIMER - This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily

constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the

United States Government or any agency thereof.

2 ESQ

9. Impact Level

Date' Received: A	INFORMATION RELEASE REQUEST Reference: WHC-CM-3-4					
7/2/93 . 1		Complete for	all Types of	Release		
Pu	rpose			ID Num	ber (include revision, volu	
[] Speech or	T	[] Reference	ce al Report	WHC-	SD-EN-SAD-026, Rev.	U
• • •	eck y one	[x] Technica [] Thesis	•	List a	ttachments.	
	fix)	Dissertation [] Manual			J D	
[] Abstract		[] Brochure		A and	а в	
[] Visual Aid			e/Database led Document	Date R	elease Required	
[] Speakers Bureau		[] Other			August 2, 199	3
[] Poster Session [] Videotape			· · · · · · · · · · · · · · · · · · ·	<u> </u>	August 2, 133	
Title Safety Assessment	for St	orage of Co	ntaminated	l Soil	Unclassified Category	Impact 2
at the 100-F Area					UC-	Level ES
						Q
New or novel (patentable) subject	matter?	[X] No []	Informa	tion rece tary data	eived from others in confident, trade secrets, and/or inv	ence, such as ventions?
Yes If "Yes", has disclosure been sub			[X] No		es (Identify)	
company?	milited D	, And Of Other	1 2.3	£3 .	. •	
[] No [] Yes Disclosure No(s).					
Copyrights? [X] No [] Yes			Tradema	rks?	- Addings Towns Char	r and
If "Yes", has written permission		nted?	Emora	ONCY D	es (Identify) TerraStor rediction Information	i allu In
[] No [] Yes (Attach Permissi	on)	0				/11
Title of Conference or Meeting		Complete for	Speech or Pre		Sponsoring	
litte of Conterence or Meeting			1 3,000		- _{- г}	
Date(s) of Conference or Meeting	City/S	tate	l Wi	ill proce	edings be [] Yes	[] No
pate(5) of conference of meeting	","		pu	ublished?	[] Yes	II No
			i		ial be handed	F 3
			01	ut?		
Title of Journal						
			T FOR C10U4TO	DIEC		
	V		ST FOR SIGNATO		icates Approval	
Review Required per WHC-CM-3-4	<u>Yes</u>	<u>No</u> <u>Re</u>	Name (print		Signature	<u>Date</u>
Classification/Unclassified		F7				
Controlled Nuclear Information	[]	[x]		1/22	11 c Allahamen	8/31/93
Patent - General Counsel	[]		GC Memo 2/		H.E. Margney	0/2//22
Legal - General Counsel	[]	[x] <u>00</u>	GC Memo 2/	14193	H.E. Margney	2/31/93
Applied Technology/Export					v	
Controlled Information or International Program	ſΊ	[x]				
WHC Program/Project	ΪÌ	[x]				
Communications	[]	[x]			This signifu	v? —
				02.00	en acknewledge	
RL Program/Project	[x]	[] _	7111		<u> </u>	
Publication Services	[x]	L		1	the existing	0 1 0
Other Program/Project	[]	[x] G	1 Craw	torc	7 44-314-214	autou Te
Information conforms to all appli		quirements. Th			certified to be correct.	GILLY, CUE
	Yes		ř		ELEASE ADMINISTRATION APPRO	
References Available to Intended	[X]	[]	Stamp is req	uired bei	ore release. Release is co	ontingent upon
Audience	E 3		resolution o	† mandato	ory comments.	
Transmit to DOE-HQ/Office of						
Scientific and Technical Information	[]	[x]		ثق	FOR TO	
Author/Requestor (Printed/Signatu		Date			ST FRICE OF	
	2111				0. 7. 1.	
J. A. Locklair MKL	Waller	9-293		a d	$\mathcal{I}_{\mathcal{L}}\mathcal{D}$	
Intended Audience				A C	100	
	M	enal		1	in ha	
[] Internal [] Sponsor		ernal		, g	9/9/	
Responsible Manager (Printed/Sign		Date			1.1	
N P Karr		9.1.93	Date Cancell	ed	Date Disapprove	ed

CONTENTS

1.0	INTRODUCTION AND SUMMARY
2.0	WORK SCOPE
3.0	HAZARDS INVENTORY
4.0	NATURAL PHENOMENA
5.0	POTENTIAL ENERGIES OF CONCERN
6.0	SITE DESCRIPTION
7.0	HAZARDS ASSESSMENT
8.0	GPERATIONAL SAFETY LIMIT
9.0	REFERENCES
APPEI	NDIXES
A B C	SUPPORTING CALCULATIONS
TABLE	ES
1 2 3	116-F-4 Pluto Crib Radionuclide
FIGUE	RES
1 2 3 4	Orientation of the Hanford Site

This page intentionally left blank.

SAFETY ASSESSMENT FOR STORAGE OF CONTAMINATED SOIL AT THE 100-F AREA

1.0 INTRODUCTION AND SUMMARY

Westinghouse Hanford Company (WHC) is responsible for managing the investigation, characterization, and remediation of the Hanford Site for the U.S. Department of Energy. For environmental restoration (ER) and decontamination and decommissioning (D&D) remediation activities that involve large quantities of soil, it may become necessary to store contaminated soil on a temporary or semipermanent basis. This safety assessment addresses the hazards associated with storage of contaminated soil from a retired liquid waste disposal (LWD) site under these conditions.

The ER projects involving removal of contaminated soil from a crib, trench, ditch, or pond may subject soil to storage on an interim basis during excavation, characterization, processing, or disposal phases of a particular project. Earth-moving equipment (such as backhoes) will be employed to move quantities of soil from the project site to transport vehicles that will transport the soil to a processing unit. Depending on the process, soil may be stored to await characterization, transport, processing, or after processing if contaminants of concern were not fully addressed.

A temporary soil storage unit has hazards associated with any soil activity. These hazards are a function of hazardous material quantity and credible mechanisms available that could disperse these materials. Resuspension of contaminants by credible mechanisms such as wind erosion, loss of confinement, and biointrusion have been identified. Contaminants of concern include a variety of radiological and chemical species identified at the Hanford Site. Concentrations of radionuclides typically are in the nCi to pCi per gram range. Chemicals in Hanford Site soil are generally in the parts per million or parts per billion range. There are locations at the Hanford Site where these levels are exceeded, but those locations are not included in the scope of this assessment.

The storage unit project evaluated in this assessment has been categorized as a low hazard activity in accordance with the criteria provided in WHC-CM-4-46, Nonreactor Facility Safety Analysis Manual. Review and authorization levels are anticipated to be commensurate with this hazard classification (DOE 1986). Requirements for control of soil that exceed minimum levels will be provided in the following work procedures: Job Safety Analysis, Radiation Work Permits, Hazardous Waste Operations Permit, and applicable procedures in WHC-CM-7-5, Environmental Compliance Level, WHC-CM-7-7, Environmental Investigations and Site Characterizations Manual, and WHC-CM-4-40, Industrial Hygiene Manual. This safety assessment satisfies the requirements of DOE Order 5481.1B, Safety Analysis and Review System (DOE 1986).

2.0 WORK SCOPE

Engineered containment systems provide storage of radiological and chemically contaminated soil pending resolution of characterization or

processing requirements. The objective of this activity is to store contaminated soil from inactive *Comprehensive Environmental Response Compensation and Liability Act of 1980* (CERCLA) LWD sites in a TerraStor¹ modular-constructed containment unit near the excavation site. Based upon the most limiting component of the unit, its outdoor life will not exceed five years.

Soil from the LWD sites will be transferred to the containment unit via truck, backhoe, or other mechanized methods. Soil would be contained in a maximum size 27 m by 27 m by .6 m (90 ft by 90 ft by 2 ft) unit; however, because of specific applications here at the Hanford Site, and the modular design, the unit may be constructed on a smaller scale.

The unit will have an underlayment of 100 mil geotextile and a 30 mil polyvinyl chloride (PVC) liner will be placed over it. The PVC liner has a life of five to seven years, therefore limiting components as the cover may be replaced at a later date. The unit will be covered with a 12 mil polyethylene laminate cover that has an outdoor life of approximately four to five years.

The selected excavation and storage site is the 116-F-4 Pluto Crib, located at the southern perimeter fence, within the 105-F Reactor Building exclusion area fence. The crib is approximately 36 m (120 ft) southwest of the 105-F Reactor Building. The TerraStor storage unit will be located within the fenced exclusion area for control purposes.

The excavation area is estimated to contain $3.44 \times 10^6 L$ (4,500 yd³) of potentially contaminated soil, with $3.44 \times 10^5 L$ (450 yd³) of that volume estimated to be contaminated with radioactive nuclides from fuel cladding failures. Clean soil will be stockpiled and used for backfill after completion of the storage activities and verification that all contaminants have been removed from the excavation area..

3.0 HAZARDS INVENTORY

Inventories of concern for the 116-F-4 Pluto Crib were associated with aqueous waste containing radioactive nuclides and chemical constituents from fuel cladding failures during operation of the 105-F Reactor Building. From 1952 to 1953, it is estimated 4,001 L (1,057 gal) of contaminated water was discharged into a 3 m by 3 m by 3 m (10 ft by 10 ft by 10 ft) pit that was later designated as the 116-F-4 Pluto Crib.

Table 2 lists the radionuclides from the potentially contaminated soil column in the 116-F-4 Pluto Crib.

¹TerraStor is a registered trademark of ModuTank, Inc., Long Island City, New York.

Table 1. 116-F-4 Pluto Crib Radionuclide.

Radionuclide	Average pCi/g	Curies		
²³⁸ Pu	4.7 E-01	5.6 E-04		
^{239/240} Pu	3.5 E+01	4.2 E-02		
⁹⁰ Sr	1.1 E+03	1.3 E+0		
³ H	1.4 E+03	1.7 E-02		
¹⁵² Eu	8.9 E+0	1.1 E-02		
⁶⁰ Co	4.7 E-01	5.6 E-04		
¹⁵⁴ Eu	4.0 E+01	4.8 E-02		
¹³⁴ Cs	2.1 E+01	2.5 E-02		
¹³⁷ Cs	1.6 E+03	1.9 E+0		
¹⁵⁵ Eu	9.4 E+01	1.1 E-01		
V	1.3 E+0	1.6 E-03		
Total curies = 3.5				

The potential chemical contaminant of concern is chromium, originating as an algicide in the cooling water. It is estimated that .004 kg (4 g) of sodium dichromate was disposed into the 116-F-4 crib during operations. The percent by mass of chromium would therefore be 0.002 kg (1.59 g); this information was obtained from the Waste Information Database System (WIDS). The WIDS is controlled and maintained by WHC. The amount of chromium would not pose a hazard to involved facility workers. In addition, the hexavalent state of the most restrictive chromium ion will react with other constituents in the sodium dichromate soil column site.

4.0 NATURAL PHENOMENA

The effect of natural phenomena was assessed relative to the activities involving excavation and storage of contaminated soil from retired LWD sites. Natural phenomena events such as floods, tornadoes, and lightening would not have significant adverse effects that would increase the hazards associated with storage activities. Statistics and probability scopes for these events at the Hanford Site are provided in Lehrschall (1992).

High wind speeds up to 180 km/hr (112 mi/hr) have been determined to be credible for the Hanford Site (> 10×10^{-6}) (Kennedy et al. 1990). Normal wind speeds of 4.8 km/hr (3.0 mi/hr) were found not to have an effect. An analysis at the BX-102 site involving a fractional release of the highest concentrations of radionuclides from three drive barrels exposed to a 24 km/hr (15 mi/hr) wind for 1 hour and 8 hour found the consequences to the onsite worker and the public to be insignificant (Lehrschall 1992). TerraStor installation activities would be expected to encounter concentrations of nuclides in nCi to pCi per gram range versus the uCi/g concentrations at the

BX-102 site. The 24 km/hr (15 mi/hr) wind speed is the maximum wind speed under which outdoor work activities are allowed. Missiles generated by high winds could generate hazards to workers or damage support equipment; however, because of the type of activities performed, high winds would not lead to surface spills or airborne releases. The consequences associated with high winds/missiles would be bounded by the maximum release event.

5.0 POTENTIAL ENERGIES OF CONCERN

The focus of this assessment is the storage of contaminated soil from retired LWD sites. The energies necessary to redistribute those soil in a manner that would be detrimental to the health and welfare of the public, the onsite worker, or the environment are discussed in this section.

Credible mechanisms for release of contaminated soil include wind erosion, biointrusion, and failure of containment with subsequent erosion via wind. The system was examined for failure modes induced by a 70 mi/h wind and found to be more than sufficient to withstand the pressures created by this phenomena. Calculations for wind induced pressures indicate that the cover could withstand pressures 50 times greater than those generated by a 70 mi/h wind (Attachment C). Additionally, a crusting agent will be used on the soil impounded in the Terrastor unit. The crusting agent will prevent soil erosion if a cover failure occurs.

These energies could induce transfer of contaminants to other than desirable locations. The transfer of soil from project sites to storage may result in small quantities being lost in transport. However, these quantities will be bounded by the assessment envelope.

Other mechanisms considered were range fires, tornados, floods, seismic events, lightning strikes, and accidents from vehicles. It was postulated that the movement of the maximum concentration of radionuclides would be induced by wind erosion under ideal conditions. Therefore, wind erosion of the maximum soil storage area (unmitigated) will be used as a basis for evaluating the consequences of this storage activity.

6.0 SITE DESCRIPTION

6.1 REGIONAL BACKGROUND

ı

This section provides a categorical list of references for detailed studies on the regional background of the Hanford Site.

- Meteorology Delaney et al. (1991) and PNL 1990
- Geology Delaney et al. (1991)
- Hydrogeology Liikala et al. (1988).

The topography of the Hanford Site is relatively flat although elevations range from greater than 1,000 m (3,300 ft) above mean sea level (msl) at Rattlesnake Mountain to 119 m (390 ft) above msl along the Columbia

River. The 100-F Area is situated along the Columbia River in the northern portion of the Hanford Site with an elevation of 119 m to 143 m (390 ft to 470 ft). The gradient increases slightly away from the river channel.

There are no permanent residents on the Hanford Site. The working population of the 100-F complex varies on a daily basis. Generally, however, the population averages approximately 10 people per day in the area. There are boaters who use the Columbia River for recreation throughout the year and have access to the west and south banks of the river. The nearest public road is State Highway 24, located 8.9 km (5.5 mi) from the 100 F Area. The nearest resident to the 100 F Area is located 8.1 km (5 mi) east of the reactor and across the Columbia River.

The Hanford Site is located in south-central Washington State, approximately 273 km (170 mi) southeast of Seattle and 201 km (125 mi) southwest of Spokane (Figure 1). The site occupies an area of approximately $1,450~{\rm km}^2$ (560 mi²) within the semiarid Pasco Basin of the Columbia Plateau.

6.2 LOCATION AND DESCRIPTION

This section describes the location of the TerraStor unit with respect to the Hanford Site. Figure 1 provides a basic orientation of the Hanford Site and Figures 2 and 3 provide maps of the 100-F Area. Figure 4 depicts specifically within the 100-F complex where the TerraStor unit will be located.

7.0 HAZARDS ASSESSMENT

The hazard associated with the storage of soil contaminated with radionuclides is potential inhalation of particulates. Therefore, this analysis will focus on the concentrations, mechanisms, and risks associated with particulate inhalation.

It is assumed the storage area will be uncovered and the soil will have a homogenous mixture of contaminants. The soil will be dry with the top centimeter subject to wind erosion. The potential exists for resuspension from transport of soil to storage; however, the total area of the TerraStor storage module unit will present a larger source term for resuspension of particulates. Because the storage area presents the largest area for resuspension of particulates, it will be used as the bounding source term for this assessment. Appendix A provides supporting calculations for the TerraStor storage unit. The safety classification for the unit is provided in Appendix B.

There are no known chemical species for which consideration of source terms would be evaluated. If chemical contaminants are identified during the activities, work will cease until those hazards are evaluated.

Figure 1. Orientation of the Hanford Site.





Figure 2. Location of 100 F.







Figure 4. Siting Within the 100 F Area.



The consequences of a resuspension of particulates are listed below in Table 2. Table 3 lists the upper limits for low hazard operation in accordance with WHC-CM-4-46. The derived air concentration guides (DAC) value applies to facility workers, and is based upon an annual estimated dose equivalent (EDE) of 5 rem. The derived concentration guides (DCG) value applies to the public and is based upon an annual EDE of 0.1 rem. Therefore, at 100 m (330 ft) using the most conservative model available, the air concentration for the most limiting isotope within the storage unit would not reach a DCG level requiring public concern. Consequently, exposure to site workers, uninvolved site workers, and the public would be well below the upper limit of risk for low hazard activities as specified in WHC-CM-4-46.

Table 2. Airborne Concentration Of Radionuclides.

Nuclide	Concentration at 100 m (330 ft) in uCi/cc	DAC value in uCi/cc	DCG value in uCi/cc
⁹⁰ Sr	1.9 E-11	2.0 E-9	9.0 E-12
¹³⁷ Cs	2.77 E-11	7.0 E-8	4.0 E-10

Table 3. Hazard Threshold Values.

· · · · · · · · · · · · · · · · · · ·	1	esilutu vatues.	<u> </u>
Hazard category	Facility worker		
	General u	se	
Radiological	<exempt quantity</exempt 		
Chemical	none listed	<0.1 IDLH	<0.01 IDLH
	Low hazaı	rd	
Radiological	≥Exempt quantity <25 rem	≥0.1 rem <5.0 rem	≥0.01 rem <0.5 rem
Chemical	none listed	<u>></u> 0.1 IDLH	≥0.01 IDLH

IDLH = immediately dangerous to life or health.

The Emergency Prediction Information² program model has generated data that confirms the potential for ingestion of radiological particulates is low and the storage of soil in the unit constitutes a low hazard activity. The risk is well within the low hazard regime and will not pose an unacceptable threat to the public, workers, or the environment. Although the program model assumes unmitigated circumstances, the suppression of soil to prevent dispersion by wind erosion will be incorporated into the operational safety limit (OSL) to further lower the potential for lofting particulates.

²Emergency Prediction Information is a registered trademark of Homann Associates, Inc., Fremont, California.

8.0 OPERATIONAL SAFETY LIMIT

The following required safety function limits the potential for resuspension of particulates from the storage site and will assure the limits for occupational safety are not exceeded. The function encompasses monitoring for control purposes and administrative documentation to ensure requirements are met. By implementation of a safety function, the safety envelope of this assessment will remain a low hazard activity, thereby assuring compliance with DOE directives.

<u>Operational Safety Limit 1 - Dust Suppression of Soil</u>

- 1.0 Title Limiting the Potential for Resuspension of Particulates.
- 1.1 Applicability This OSL applies to potentially contaminated soil removed from LWDS.
- 1.2 Objective To assure the storage of LWDS soil inventories are controlled, and the potential for resuspension of particulates is minimized from these sites.
- 1.3 Requirements a. Dust suppression techniques shall be used to prevent resuspension of contaminants (e.g., water, sarfactents, crusting agents, and covers).
 - b. The responsible safety officer or field team leader will assure that appropriate personnel are available for monitoring and controlling soil inventory.
- 1.4 Surveillance The responsible operating organization shall verify daily during operation and at least weekly (plus or minus one day) during interim storage that the project site is in compliance with the requirements of this OSL. Surveillance data results shall be documented in an auditable log or Field Activity Report (FAR).

1.5 Recovery -

1.5.1 Noncompliance with the Requirements of the Operational Safety Limit

- a. If field surveys indicate migration of contaminants from the storage area, activities shall stop and the area shall be stabilized.
- b. If dust suppression techniques are not available, activities shall stop and stabilization methods shall be implemented.
- c. In the event monitoring support is not available at the project site, work shall immediately

cease; notification to appropriate line and health physics management is required. Monitoring support is required before restart of operations with concurrence of the site safety officer and health physics.

d. The OSL violation shall be documented as required by WHC-CM-1-3, Management Requirements and Procedures.

1.5.2 Noncompliance with Surveillance Requirement

- a. Surveillance shall be performed immediately.
- b. If the surveillance indicates noncompliance with the requirements in Section 1.3 of this OSL, the recovery action in Section 1.5.1 shall be implemented.
- c. Failure to document the surveillance requirement shall be documented as required by WHC-CM-1-3.
- 1.6 Audit Point An auditable log or FAR shall be maintained to document the results of surveillances. This log should be reviewed weekly by the operations organization to assure compliance with the OSL.
- 1.7 Basis Compliance with these OSL requirements will assure the safety scope of this assessment is maintained and activities will remain a low hazard.

9.0 REFERENCES

- Comprehensive Environmental Response, Compensation, and Liability Act of 1980, 42 U.S. C. 9601 et seq.
- DOE, 1986, Safety Analysis and Review System, DOE 5481.1B, U.S. Department of Energy, Washington, D.C.
- Kennedy, R. P., S. A. Short, J. R. McDonald, M. W. McCann, R. C. Murray, J. R. Hill, 1990, Design and Evaluation Guidelines for Department of Energy Facilities Subjected to Natural Phenomena Hazards, UCRL-15910, U. S. Department of Energy, Washington, D. C.
- Lehrschall, R. R., 1992, Safety Assessment for Environmental Investigations and Site Characterizations, Volume 1: Activities Involving Drilling and Sampling of Contaminated Soil, WHC-SD-EN-SAD-016, Rev. 0, Vol. 1, Westinghouse hanford Company, Richland, Washington.
- Liikala, T. L., R. L. Aaberg, N. J. Aimo, D. J. Bates, T. J. Gilmore, E. J. Jensen, G. V. Last, P. L. Oberlander, K. B. Olsen, K. R. Oster, L. R. Roome, J. C. Simpson, S. S. Teel, and E. J. Westergard, 1988,

- Geohydrologic Characterization of the Area Surrounding the 183-H Solar Evaporation Basins, PNL-6728, Pacific Northwest Laboratory, Richland, Washington.
- PNL, 1990, Climatological Summary of Wind and Temperature Data for the Hanford Meteorology Monitoring Network, PNL-7471, 1990, Pacific Northwest Laboratory, Richland, Washington.
- WHC-CM-4-40, *Industrial Hygiene Manual*, Westinghouse Hanford Company, Richland, Washington.
- WHC-CM-4-46, Nonreactor Facility Safety Analysis Manual, Westinghouse Hanford Company, Richland, Washington.
- WHC-CM-7-5, Environmental Compliance, Westinghouse Hanford Company, Richland, Washington.
- WHC-CM-7-7, Environmental Investigation and Site Characterizations Manual, Westinghouse House Hanford Company.

1

This page intentionally left blank.

APPENDIX A

SUPPORTING CALCULATIONS

TerraStor tank dimensions are

90 ft by 90 ft by 2 ft = $16,200 \text{ ft}^3 \text{ or } 600 \text{ yd}^3$.

The volume of soil in the 116-F-4 Pluto Crib is

20 ft by 20 ft by 25 ft = $10,000 \text{ ft}^3 \text{ or } 370.37 \text{ yd}^3$.

The volume of the top centimeter of soil subject to resuspension is $90 \text{ ft by } 90 \text{ ft by } 0.0328 \text{ ft } = 266 \text{ ft}^3.$

The area of the top centimeter of soil subject to resuspension is $90 \text{ ft by } 90 \text{ ft} = 8.100 \text{ ft}^2$.

Where the area of the circle is

 $1/4 \text{ pi } D^2 = \text{area}$

 $8,100 \text{ ft}^2 = 1/4 \text{ pi diameter}^2$

 $\frac{8.100 \text{ ft}^2}{1/4 \text{ pi}} = \text{diameter}^2$

101.6 = diameter

1/2 diameter = radius

The radius (parameter for model input) is

50.8 ft or 15.5 m.

The wind velocity (parameter for model input) is

13 mj/hr or 5.8 m/s.

The conversion of the top centimeter of soil to grams is

 $266 \text{ ft}^3 = 7.53 \text{ E}^6 \text{ cm}^3.$

(7.53 E^6 cm³) x (2 g/cm³) = 1.5 E^7 g of soil subject to resuspension.

The release rate (parameter for model input) is

$$(1.5 E^7 g) \times (3.5 E^{-6}) = 5.2 E^1 g/s.$$

The average concentration of nuclides in soil is

137
Cs 1.6 E^3 pCi/g or 1.6 E^{-9} Ci/g

 90 Sr 1.1 E^3 pCi/g or 1.1 E^{-9} Ci/g.

The fraction of specific activity is

Sr $1.1 E^{-9}$ Ci/g in soil = 4.0 E^{-12} 2.78 E^{2} Ci/g (specific activity)

Cs $\frac{1.6 E^{-9} Ci/g \text{ in soil}}{8.66 E^{1} Ci/g}$ = 1.9 E^{-11}

The release rates in grams is

$$(4.0 E^{-12}) \times (52 g/s) = 2.08 E^{-10} g/s Sr$$

$$(1.9 E^{-11}) \times (52 g/s = 9.88 E^{-10} g/s Cs.$$

The conversion of mg/m^3 in air back to uCi/cc in air is explained in the following example.

 90 Sr at 100 m concentration in air equals 6.7E $^{-11}$ mg/m 3

$$\frac{6.7 \text{ E}^{-11} \text{mg/m}^3}{1.0 \text{ E}^6 \text{ cc/m}^5} = 6.7 \text{ E}^{-17} \text{ mg/cc}$$

 $(6.7 E^{-17} mg/cc) \times (1 g/1000 mg) = 6.7 E^{-20} g/cc of {}^{90}Sr in air.$

The specific activity of 90 Sr is 2.78 E^2 Ci/g; therefore

 $(6.7E^{-20} \text{ g/cc}) \times (2.78 \text{ E}^2 \text{ Ci/g}) = 1.9 \text{ E}^{-17} \text{ Ci/cc of }^{90}\text{Sr in air or}$ $1.9 \text{ E}^{-11} \text{ uCi/cc}.$

The DAC for 90Sr equals

 $2.0 E^{-9} uCi/cc$ in air.

The DCG for 90Sr equals

 $9.0 E^{-12}uCi/cc$ in air.

APPENDIX B SAFETY CLASSIFICATION OF TERRASTOR STORAGE UNIT



From:

Risk Assessment Technology

29220-93-026

Phone: Date:

6-9236 H4-65 June 14, 1993

Subject:

SAFETY CLASSIFICATION OF TerraStor CONTAINMENT SYSTEM

TO BE, USED FOR THE 100 AREA EXCAVATION TREATABILITY TEST PLAN

To:

J. A. Locklair

H4-67

cc:

M. D. Zentner

H4-65

File/LB

Reference: (1)

1) Safety Classification of Systems, Components and Structures, WHC-CM-1-3, MRP 5.46, Rev. 4

The TerraStor containment system is a Safety Class 3 structure when utilized for the "100 Area Excavation Treatability Test Plan". The containment will be susceptible to wind and/or vehicle damage. Material resuspension and release to the environment could occur.

The volume of material represents an extremely low hazard to personnel. The low quantity of radioactive material and conditions needed for a release represent more of a dust problem. The Adverse Environmental Impact for Safety Classification, Reference 1, Appendix C, was calculated to less then 500,000 or Safety Class 3.

This evaluation is only for use of the TerraStor containment system as part of the 100 Area Excavation Treatability Test Plan and any other use of the system must be evaluated for safety classification.

Documents reviewed:

- 1. DOE/RL-93-04, Decisional Draft, 100 Area Excavation Treatability Test Plan
- 2. ModuTank Inc., TerraStor Details

N. L. Wilson

Advanced Engineer

sl

This page intentionally left blank.

APPENDIX C DESIGN CALCULATIONS

1.

From:

Facility Systems Engineering

JSB-23450-93-003

Phone:

2-0696 H5-58 June 10, 1993

Date: Subject:

100 AREA SOIL HOLDING CONTAINER

To:

L. M. Bergman H6-05 J. M. Frain H6 - 04

H5-58 mc cc: D. M. Chenault H5-72 J. I. Dearing L. L. Hyde H5-58 H6-05 J. G. Woolard

> JSB LB/File

The purpose of this letter is to describe the methods and results of the calculation performed to support the 100 Area Excavation Test. Attached are two items: A set of calculations performed to support the selection of a cover material and anchorage; and a letter transmitting the findings of a structural engineer asked to investigate the structural integrity of the container.

The calculations supporting the cover material selection and anchorage were performed assuming a 70 mph wind condition. The loads due to this wind resulted in a uniform pressure of 13 lb/ft^2 . The maximum tensile load in the plastic was then found to be 672 lb/ft. It recommended that material XR-5 model 8130 be used in this application. This material has sufficient strength to withstand this load and also has good environmental resistance. Detailed information on this material can be found in the attachments to the calculation.

The letter transmitting the results of the structural integrity investigation can be summarized as: The walls of the storage container are not adequate to support the weight of the excavated soil without back filling the area outside the walls. Also, because of the back fill, the container need not be analyzed for a seismic event. A copy of this letter can be found as Attachment two.

In conclusion, the tank can be used if adequate back filling is performed around the outside of the tank. The cover material should have a seam strength in excess of 672 lb/ft. It is recommended that a sheet of XR-5 (available from both MODUTANK or SEAMANS Inc.), be purchased with dimensions greater than 106 ft X 56 ft. The anchorage scheme for the cover is sketched in the calculations.

Please feel free to call me if you have any questions or concerns.

#5 Bengers 6/10/93 J. S. Burgess, Engineer

Component Structural Analysis

ModuTank Inc., Long Island City, New York.

1) Drawing	(2) Doc. No	(3) Page of 7
		(6) Job No.
	SOU CONTAINE	
(8) Originator <u> </u>	RUFES	Date 6/10/93
(9) Checker L. Ly	de	Date <u>6/10/93</u>
(10) PURPOSE:	SELECT TH	E COVER MATERIAL
ADD AD	CHORAGE M.CT.	HOD BASED ON A
70 mph. u	JIND LOND.	्र विकास के सम्बद्धा कर के प्रशासन के किया के किया के किया के किया किया के किया किया किया किया किया किया किया क स्थानिक किया किया किया किया किया किया किया कि
, and the first of the same community of the	ال المارون المارونيين و المراشية حما فيسور المعاصرة والاحترارة المعامدة المارونية	
REFEREL	CES	
ASCE	1990, "MINIMUM D AUD OTHER STR STANDARD 7-BB,	ESIGN LOADS FOR BUILDINGS DITUEES ! A USI/ASCE AMERICAN SOCIETY OF TS, NEW YORK,
	CH, O.W., 1956, "HA	WILEY & SONS INC., NY.
LDEEN	ER, 12.M., 1988, "DES 2" EDITION, PEE	NTICE HALL, NJ.
ROARK	J. R. J., 1954, "FO STRAIN," J'ED	EMULAS FOR STRESS AND MON, MCGRAW HILL, N.Y.
	• • • • • • • • • • • • • • • • • • • •	

SCHEMATIC



(1) Drawing _	(2) D	oc. No	(3) Page 7	01 7
(4) Building		ev	(6) Joh No	_01
(7) Subject	100 AREA SOIL C	DNTHINEZ	-	
(8) Originator	J.S. BURGESS		Date 6/10/93	
(9) Checker	L. Hyde		Date 6/10/93	
(10)	CHOWNTE 101		<u> </u>	<u> </u>
17-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-			70 mph wind	
لللبر	USING ANGI/AS P= Zn [(4CA)-6C	CE 7-88	CHAPTER G. (TABLE 4, COMP. &	(LAD., K46)
•	94 = 0. BOX 56 'Ka = 0.80 I = 0.95 V = 70 mp	Kz (IV)Z	(eg-3, SEC. 6. (TABLE 6, EXPOS (TABLE 5, CATEG (FIGURE 1)	5.1) DeE C)
: !	$g_h = 0.00256$ $g_h = 9.1$ $g_{h} = 9.1$ $g_{h} = 0.0$	25	(TABLE 9, CONS SEE TABLE 4, NOTE 1 SEASON ACP 15 +	
	P=9.056768[(=1,2) - (0,2	25)]	
	P=-	13.13 psf	•	

(1) Drawing	(2) Doc. No	(3) Page <u>3</u> of <u>7</u>
		(6) Job No
(7) Subject	ALEA GOLL CONTAIN	CP
(8) Originator	.S. BURGESS	Date 6/10/93
(9) Checker	L. Hylle	Date 4/10/93
CA	MODEL THE COVER	OUTS IN COVER
	OF AN CLUPTIC !!	PRESSURE VESSIE.
SCHI	EMATIC	
	coma,	
	Pressura	e (p) = 13.13 psf
		•
		WILLIAM WILLIAM IN THE STREET
	90.25	. 41.25
		Radius (R2)
		+
	Radius (R1)	
•	+	, ·
	ادران پرتها معاطر در دروان می ایاد در میکند در میکند در در در در در	en de la companya de La companya de la co


(1) Drawing	(2) Doc. No.	(3) Page <u></u>	-t -
(4) Building	(5) Rev.	(6) Joh No.	· OT
(7) Subject	AREA SOIL CONT	(0) 100 NO.	
(8) Originator 3, 5	LUVRACSS	Date 6/10/93	
(9) Checker	L. Hode	Date 6/10/93	
(10)		ATTIMITY OF LITTING	
FIN	D PADIL (USING	ESHBACH TABLE 1, 6,	#9)
الماسينية الماسين	= 442+12		··•·
	8 h		
	P.= 4(3.841)+(90.	2512	المالية الماكر
	8 (3.841)	25)2 R2 = 4(3.841)+(865.8	241)-
			•
	161=266,99H	R2 = 57, 29	
	<u> </u>		
<u> </u>		لويونها شتمتم والحارب والجارات والانات المراجع والمراجع	
F10/	LESULTAUIS (USINO	F POARK TAISLE XIII,	" 5")
	S/t)=(pRz)	52(t) = PR2(2-R	-
	2 /		
	$S_{1}(t) = (13.13)(57.2)$	(4) $S_2(4) = (13.13)(57.2)$	2-57.29
	2, CE) - 3 + C . // 7	/H 5(t) = 671, 57 1/4	
	OL		
		• • • • • • • • • • • • • • • • • • • •	••••
7			
は、コンプラ			
			6 lb/ft
		10000	
			1
	1111111		
i.	672 lb/ft		

* USE XIZ-5; SEAM \$ 50. 0F 200 16/14 or .2400 16/4.

(1) Drawing	(2) Doc. No		(3) Page <u>5</u> of <u>7</u>
(4) Building	(5) Rev	(6) Job	
(7) Subject <u>100 ARE</u>	A SOIL CONTAINS	- <u>P</u>	
(8) Originator 1.5.1	3004533	Date	. 4/10/93
(9) Checker	L. Hycle		6/10/93
			
•	TO PUNOUT		and a second
1 .	USE SAINDBAGS (PI		
j ::	LOOSE BACKFILL		
	SSUME FRICTION	i	
	-3012-132		
	SOIL AT.	ERADE	
	SANDBAG	S. 1111111	
	SSUME FRICTION COE	EFICIENT	BETWEEN
	COURE AND SOIL 7		
	BETWEEN COURS	و بخ الأحلالي	BAG
· · · · · · · · · · · · · · · · · · ·			
• •	•		اران المراجع ا المراجع المراجع المراج
			* 2 - 2 - 2 - 1 - 2 - 2 - 2 - 2 - 2 - 2 -
		• •	The second se
· · · · · · · · · · · · · · · · · · ·	· · · · ·	• •	
SCHEMA	TIC		en en la companya de
	BOCKFILL FOR	co IIII	• • • • • • • • • • • • • • • • • • •
1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	BACKFILL & SA	vocas	***
1			en er den den er er er de den den den den den den den den den
	+++++++++++++++++++++++++++++++++++++++		<u> </u>
	30"		
			From the more reference of the state of the
FREE BO	DX		
		a orana kababban Orana	• • • • • • • • • • ± · · · · · · · · ·
	1		
	WF.		
	F, \\\	d	
	β. (N	<u></u>	en e
	- rz		•
	L	- 1	
	C-6		

(1) Drawing	(2) Doc.	No.	(3) Page <u>6</u> of 7
(4) Building	(5) Rev.		
(7) Subject <u>100</u>	AREA SOIL		
(8) Originator	S' BURGESS		6//0/93
	L. Hyde		6/10/93
	/		7-1
(10)-	= 1/2 d (d tua p1) Y		100000000000000000000000000000000000000
عوثم سومها والأجاز الأرا	·- · · · · · · · · · · · · · · · · · ·		14
	= 4×F	e en	
613	= , w, cost tous	= (1d(# B)Y	constant
HEILETT TO THE			•
	1= /2d 1 CO5B	this /timp	((z)2(100) cos(54) tan(20)=31,0
		Tiples to berther	- tour (20) = 72,79(L)
E2-	we tand = d	Y Lten 5 = 2(1	20) L. tem (20) = 72,77(L)
F-			
[] [] [] 3	= -(T-ZFT) 5:4	Ptus = 12033	SPUTTIES DOETS
	= -Tsinptuns +		The second of th
	= -T5:4B tem 5+	Z(// chap) Si	u & trust
•	= (-67251464)+~~12	0) + (2)2(100) 5:4	(54) tun(20) = -1/2.30
· · · · · · · · · · · · · · · · · · ·			
1 1	FH=D=> TCOSB =		
	672(cos(s4))=2(31.01)cas(s	4) + 2(17,79) (-112,30)
1	/= 677 105/5d)	-2/21-61	
	L= 672 (05/54)	(272,79)	+) +116.38
	•	• • • • • • • • • • • • • • • • • • •	
	4=3:25 / 20	SF STL1.	
	AND LAY		
			
			6"
1-		1 17 17	
	TENSION IN PLAST		
A first transfer of the second	FRICTION AND	_	:
	EDITH OF COVER	COY)	- p 3 84 J
	- LENSITY OF COVE		7 4 6 M SAD X NAZZ \
L:	= LENGTH OF RUL	75/ //	

(1) Drawing	(2) Doc. No	(3) Page 7 of 7
(4) Building	(5) Rev	(6) Job No
(7) Subject	AREA SOLL CONTA	LIER
(8) Originator	SUBURGES	Date
(9) Checker	L. Hyde	Date 6/10/42
(10)		
العن	CULATE THE AMOUN	UT OF COUER MATERIAL
		- DIT - LA
 	en en de la companya	er egeneration de la companya de la Esta manda de la companya de la comp
		en en la servició de la companya de O en en en entre la granda de la companya de la co
	table for the region and the second density and the second design of the	maniferente a accominato y menerales de despresa de la composition della composition
	49	
1		
	3.81	44,25
en 199 - en	11:14	20,625
	90,25	5-7
• • • •	Parauser a promise	GULLR SHEET LXWW.Lere:
	TORON SECTION	GOLAR SHEEL LXWWIEre:
<u> </u>		in the second
	14	1 (41.25 - (3.84)] = 2057=21
		78"
		56
		\
1	= 2(21+32+5]+49=100	6 /
		The second secon
		en de la companya de Companya de la companya de la compa
		en e
	20.(25	1 K284
		(604)
	111 2 20.625 - (3) +5}	352
	+-++	
	A=L×W= 106 (56)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
)=, S.7. @S
	7	7
	Buy a she	of with dimensions/
	apt LIEP THI	AN 106 × 56
	110 x 80	AN 106 × 56 = 1500 (42)
		-/
in the second se	6600 (9)1,14	=\$ 7524 (Gor XR-5)









Figure C2. Soil Storage Unit Installation 100 Area.





.



, , , • •

This page intentionally left blank.

DISTRIBUTION SHEET										
To From		n			Page 1 of 1					
District to		A. Locklair								
						Date 7/29/93				
Project Title/Work Order				EDT No. 141686						
Safety Assessment for Storage of Area	ninated Soil at the 100-F			ECN No.						
	<u> </u>									
	MSI N	Text	Text		Attach.	EDT/E				
Name		With	Only		/	CN				
		All		l	Append	Only				
		Attac	!		ix	,				
		F	h.			Only				
M. P. Connelly		H6-06	X		1					
J. M. Frain		H6-04	Χ							
K. A. Gano R. L. Hand		X0-21	X							
G. C. Henckel		H4-16 H6-04	X							
R. P. Henckel		H6-02	X X							
D. O. Hess		L4-74	X							
G. S. Hunacek		X0-41	Χ							
W. L. Johnson N. R. Kerr		H6-04	X							
C. H. Kindle		H4-67 H6-05	X X							
A. J. Knepp		H6-06	X							
A. D. Krug		H6-02	χ̈́							
J. A. Locklair		H4-67	Χ							
J. K. Patterson R. C. Roos		H6-27	X							
C. A. Rowley		H6-04 H6-04	X X							
N. A. Skelly		H6-03	x							
L. C. Swanson		H6-06	X							
S. E. Vukelich D. J. Watson		H6-02	Χ							
J. J. Zimmer		X0-41	X							
Central Files (Original + 2)		H4-67 L8-04	X X							
Dockett Files (2)		H5-36	X							
EDMC (2) /		H6-08	Χ							
ERSS (3)		H4-67	Χ							